


Do not scale from this drawing. Only figured dimensions are to be taken from this drawing. The contractor must verify all dimensions on site before commencing any work or shop drawings. The contractor must report any discrepancies to POD NEWCASTLE LTD before commencing work. If this drawing exceeds the quantities taken in any way, POD NEWCASTLE LTD drawings. POD NEWCASTLE LTD drawings to any ordinance Survey data, or beyond the boundary of the inserted topographic survey data. Work within The Construction (Design and Management) Regulations 2015 is not to start until a Health and Safety Plan has been produced. OPPRIGHT OP DO NEWCASTLE LTD. This drawing is Copyright and must not be reproduced in any format or media without written/ verbal consent of POD NEWCASTLE LTD.









TOFFEE FACTORY | NEWCASTLE-UPON-TYNE | NEI 20F | 0191 495 7700 | INFO@PODNEWCASTLE.CO.UK
PROJECT:
Thorpe Leazes Farm

Location	Plan	

Tom Wa	lker & So	ns	Planning	
SCALE: 1:1250	SHEET SIZE:	11.23	DWN BY:	CHECKED BY:
PROJECT NO: 1450-WAL PD-00.01 PD-00.01				REVISION: