

HOLLYWOOD FARMHOUSE

CO16 9AP

Solar company's renewer's comments on possible siting of panels on the ground.

Potential Ground mount system:

Issues:-

Visible from road

Within 5 m of boundary


Significant shading from treeline

Potential Ground mount system:

Issues:-

Within 5 m of boundary

Significant shading from treeline of orchard, and from property compromises performance significantly



South facing required for solar PV