



Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.1	https://tourmkr.com/F1aZ6NgaWt/35959 329p&296.06h&80.25t	Induction Loops and Help Points on Platform 1	NTL SISS specification	2000年度	Help Point	Replace existing help point with combined induction/help point for Platform 1. Utilise existing power and comms cables. Fix to existing post or allow for a new post in acocrdance to SISS specification
2.3.2	https://tourmkr.com/F1aZ6NgaWt/35959 103p&95.8h&84.99t	Induction Loops and Help Points on Platform 2	17.2		Help Point	Replace existing help point with combined induction/help point for Platform 2. Utilise existing power and comms cables. Fix to existing post or allow for a new post in accordance to SISS specification
2.3.3	https://tourmkr.com/F1aZ6NgaWt/35959 156p&101.01h&87.01t	Induction Loops and Help Points on Platform 2/3	17.2		Help Point	Replace existing help point with combined induction/help point for Platform 2/3. Utilise existing power and comms cables. Fix to existing post or allow for a new post in accordance to SISS specification
2.3.4	https://tourmkr.com/F1aZ6NgaWt/35959 248p&296.56h&90.74t	Help Points on Platform 4	17.2		Help Point	Replace existing help point with combined induction/help point for Platform 4. Utilise existing power and comms cables. Fix to existing post or allow for a new post in accordance to SISS specification





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.5	https://tourmkr.com/F1aZ6NgaWt/35959 291p&75.28h&85.99t	Help Points on Platform 5	17.2	n	Help Point	Replace existing help point with combined induction/help point for Platform 5. Utilise existing power and comms cables. Fix to existing post or allow for a new post in acocrdance to SISS specification
2.3.6	https://tourmkr.com/F1aZ6NgaWt/35959 086p&193.6h&101.85t	Station Map & Key Local Info Board. Main entrance	NTL Design guide and NR signage guide NR/GN/CIV/300/01		Signage	Replace existing station plan / signage with free issue from NTL in existing frames. Wayfinding signage around the station yo be upgraded / enhanced to bring up to NTL and NR standard. PC to carry out detailed survey and design for the station signage. Lump sum with number of signs to be provided as part of the tender.
2.3.7	https://tourmkr.com/F1aZ6NgaWt/35959 310p&308.82h&92.97t	Station Map & Key Local Info Board. Platform 5	NTL Design guide and NR signage guide NR/GN/CIV/300/01		Signage	Replace existing station plan / signage with free issue from NTL in existing frames. Wayfinding signage around the station yo be upgraded / enhanced to bring up to NTL and NR standard. PC to carry out detailed survey and design for the station signage. Lump sum with number of signs to be provided as part of the tender.
2.3.8	https://tourmkr.com/F1aZ6NgaWt/35959 086p&193.6h&101.85t	Braille Station Maps outside platform 1	A.v1.2,RNIB 3D Braille map design guide.		Signage	New frame and posts for Braille Station Maps. Maps to be designed and produced by Contractor.





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.9	https://tourmkr.com/F1aZ6NgaWt/35959 310p&308.82h&92.97t	Braille Station Maps outside platform 5	A.v1.2,RNIB 3D Braille map design guide.		Signage	New frame and posts for Braille Station Maps. Maps to be designed and produced by Contractor.
2.3.10	https://tourmkr.com/F1aZ6NgaWt/35959 071p&51.61h&83.8t	New Accessible W/C & Baby Change Facilities	21.1		Toilet POD?	Location to be decided. Reconfiguration of existing waste bin store and relocation of bick rack to create space for the Toilet POD
2.3.11	https://tourmkr.com/F1aZ6NgaWt/35959 124p&65.28h&90.78t	Handrail Tactiles & Stair Nosings (Platform 1)	6.3, 6.5, 13.1, 18.1, 18.2, 19.1		Stairs	Stair nosings to be deep cleaned / painted / repaired / replaced (100%). Handrail to be changed to compliant double handrails. Handrails to be painted to DFT standard yellow. Approximate length of stairs 30m
2.3.12	https://tourmkr.com/F1aZ6NgaWt/35959 299p&68.61h&84.19t	Handrail Tactiles & Stair Nosings (platform 2)	6.3, 6.5, 13.1, 18.1, 18.2, 19.1		Stairs	Stair nosings to be deep cleaned / painted / repaired / replaced (100%). Handrail to be changed to compliant double handrails. Handrails to be painted to DFT standard yellow. Approximate length of stairs 30m
2.3.13	https://tourmkr.com/F1aZ6NgaWt/35959 212p&34.88h&91.7t	Handrail Tactiles & Stair Nosings	6.3, 6.5, 13.1, 18.1, 18.2, 19.1		Stairs	Stair nosings to be deep cleaned / painted / repaired / replaced (100%). Handrails to be painted to DFT standard yellow. Approximate length of stairs 30m





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.14	https://tourmkr.com/F1aZ6NgaWt/35959 310p&30.94h&96.4t	Handrail Tactiles & Stair Nosings	6.3, 6.5, 13.1, 18.1, 18.2, 19.1		Stairs	Stair nosings to be deep cleaned / painted / repaired / replaced (100%). Handrails to be painted to DFT standard yellow. Approximate length of stairs 30m
2.3.15	https://tourmkr.com/F1aZ6NgaWt/35959 208p&134.54h&88.14t	Covered Drop Off/Pick Up Point	7.1		Drop Off	Reconfigure are for a covered drop off 7M long Modify footpath, drop kerbs and road markings . Type and manufacturer to be confirmed by PC
2.3.16	https://tourmkr.com/F1aZ6NgaWt/35959 147p&250.88h&96.42t	Entrance Doors Matting & Door entrances	1, 2.2, 20.2, 21.1 24.2, 24.6, 27.4		Door Mats	Entrance door mats to be installed. 4 m2
2.3.17	https://tourmkr.com/F1aZ6NgaWt/35959 135p&100.5h&77.03t	Waiting Room / Platform Furniture on platform 2	9, 13.1, 23		Seating	Replace existing non compliant seating





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.18	https://tourmkr.com/F1aZ6NgaWt/35959 107p&38.63h&82.21t	Waiting Room / Platform Furniture on platform 3	9, 13.1, 23		Seating	Replace existing non compliant seating
2.3.19	https://tourmkr.com/F1aZ6NgaWt/35959 143p&299.93h&77.1t	Furniture Painting / Tapping Rails / Window Manifestations	10.1, 10.2, 10.3		Seating	Replace existing non compliant seating
2.3.20	https://tourmkr.com/F1aZ6NgaWt/35959 123p&288.41h&79.68t	Furniture Painting / Tapping Rails / Window Manifestations	10.1, 10.2, 10.3		Seating	Replace existing non compliant seating
2.3.21	https://tourmkr.com/F1aZ6NgaWt/35959 049p&175.9h&79.12t	Furniture Painting / Tapping Rails / Window Manifestations	10.1, 10.2, 10.3		Seating	Replace existing non compliant seating
2.3.22	https://tourmkr.com/F1aZ6NgaWt/35959 156p&57.16h&75.27t	Furniture Painting / Tapping Rails / Window Manifestations	10.1, 10.2, 10.3		Seating	Replace existing non compliant seating





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.23	https://tourmkr.com/F1aZ6NgaWt/35959 084p&291.31h&90.42t	Reconfigure Waiting Shelter / New Waiting Shelter. Platform 1	25.1, 25.2, 25.3		Waiting Shelter seating	Reconfigure existing waiting shelter (1 No) replace existing seating. Existing waiting shelter to be painted in accordance with NTL design guide where possible. Powder coated and aluminium waiting shelters to remain as existing as painting repirs will not be possible. PC to confirm.
2.3.24	https://tourmkr.com/F1aZ6NgaWt/35959 077p&6.64h&90.46t	Reconfigure Waiting Shelter / New Waiting Shelter. Platform 3	25.1, 25.2, 25.3		Waiting Shelter seating	Reconfigure existing waiting shelter (1 No) replace existing seating. Existing waiting shelter to be painted in accordance with NTL design guide where possible. Powder coated and aluminium waiting shelters to remain as existing as painting repirs will not be possible. PC to confirm.
2.3.25	https://tourmkr.com/F1aZ6NgaWt/35959 354p&304.44h&87.95t	Reconfigure Waiting Shelter / New Waiting Shelter. Platform 4	25.1, 25.2, 25.3		Waiting Shelter seating	Reconfigure existing waiting shelter (1 No) replace existing seating. Existing waiting shelter to be painted in accordance with NTL design guide where possible. Powder coated and aluminium waiting shelters to remain as existing as painting repirs will not be possible. PC to confirm.
2.3.26	https://tourmkr.com/F1aZ6NgaWt/35959 252p&103.72h&95.71t	Reconfigure Waiting Shelter / New Waiting Shelter. Platform 5	25.1, 25.2, 25.3		Waiting Shelter seating	Reconfigure existing waiting shelter (1 No) replace existing seating. Existing waiting shelter to be painted in accordance with NTL design guide where possible. Powder coated and aluminium waiting shelters to remain as existing as painting repirs will not be possible. PC to confirm.





Item Ref:	Link to 360 location online	Works Description	NTL Design Guide Ref:	Location Image	Asset List:	Approximate Quantities / Specification
2.3.27	N/A	Wayfinding - New Assets - PODS & Drop Offs to NTL/NR Standard	NTL Design guide and NR signage guide NR/GN/CIV/300/01	N/A	N/A	Wayfinding signage around the station to be added in relation to new significant assets installed, WC POD and Covered Drop Off. NTL Design Guide and NR standard to be used. PC to carry out detailed survey at delivery and new signage to be agreed with and signed off by Station Manager. Total price to survey, design, supply and fit with approximate number of signs to be provided in the pricing schedule.