

## Design and Access Statement

The reason the windows have been replaced at said property is that a storm blew out one window and upon investigation the second window was deemed extremely dangerous and would possibly be blown in as well. There has been no impact on the neighbouring properties. This is a grade two listed property and the work carried out has been like for like.

Tending District Council  
Collected by

23 OCT 2023

Courier