

View looking out from Second Floor Landing of Stairwell Block depicting the condition of existing windows

# <u>Notes:</u>

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.

Planning Application Detail for Rear Elevation Windows At: Hawks Mill Hawks Mill Street Needham Market Suffolk IP6 8LU

**PHOTO 01** 



View of the Rear Elevation of the West Side of Hawks Mill. The two windows serving Flat 6 are highlighted

# Notes:

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.





View of the Rear Elevation of Hawks Mill, as seen from Car Park. The two windows serving Flat 6 are highlighted

#### Notes:

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.





Example of window type, taken from Ground Floor Rear Elevation of Hawks Mill

### <u>Notes:</u>

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.





Actual window serving Flat 6, taken from Ground Floor Rear Elevation of Hawks Mill

# Notes:

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.





Actual window serving Flat 6, taken from Ground Floor Rear Elevation of Hawks Mill

### Notes:

Windows to be removed with care, no alteration to made to apetures. Any damages caused during removal of existing fenestration to be made good with identical materials and finishes as existing.

