

- All internal walls are to be inspected on site to determine whether they extend through the ceiling to the floor above.
- Any walls that do not extend above ceiing level must be fitted with cavity barriers to comply with building regs clause 9.5 A0B V2.

2302