

## EXISTING CRICKET NETS AT NEWPORT RECREATION GROUND

As can be seen from the separate picture the existing cricket nets are in a state of disrepair and only one of the lanes has any form of netting. Hence only the lane on the right can be used. The surface of the left hand lane needs replacing if it is to be brought back into use. All the netting requires replacement.