

Heritage statement

Repair of current dormer window at 9 Tynemouth Place

We are just repairing the current dormer window. Because some of the wood is rotten, bits will need replacing but these will be like for like so the design and appearance will not change.

This repair will have no effect on the look or heritage value of the property