Stone replacement indent. Lime mortar surface repair. Descale loose / friable stone. Crack fill. Crack stitch and fill.



ELEVATION 2

Notes:

The contractor is to verify all buildings and site dimensions prior to commencement of works or preparation of shop drawings.
This drawing and the building works depicted are COPYRIGHT of TRIDENT and may not be reproduced except by written permission,

Use only figured dimensions Do not scale

Note:

Existing windows are to undergo refurbishment including overhauling and redecoration. Repairs will be undertaken on a like for like basis to match existing materials.

| PLANNING |
|----------|
|----------|

| Revision: | Date: | Description: | Checked: | |
|-----------|----------|-------------------------------|----------|--|
| Α | 09.01.24 | Window note added to drawing. | MS | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Client:

Ambassador Theatre Group

Property:
Kings Theatre
Bath Street
Glasgow

External Masonry R

External Masonry Repairs Elmbank Street Elevation

| Job No: | Drawn by: | Scale: |
|-------------|-----------|----------|
| P2023-0422 | MD | A1@1:100 |
| Drawing No: | Date: | Checked: |
| P002 | Dec 2023 | MS |

Trident Building Consultancy Ltd.
Queen's House
19 St. Vincent Place
Glasgow
G1 2DT
Tel: 0141 229 4525
www.tridentbc.com

