

GENERALLY

Refurbish roof and insulate - see A(20)-03 repair/ replace any damaged slates & flashings new matching fascias if necessary and cast iron rw goods to match existing
See Clement conservation rooflight drawings D-CRPM-01 to 04
& Leadworx drawing 03 for Roof Vents

Conservation and roof notes added

СМ

12/03/24

20

30

40

20

first issue

Author

St. Andrew, High St, Llandaff, CF5 2DX Matthew Skuse

GA Plan Roof

job no. drawing no. rev A

status Information

scale @ A3 On 1 : 100

