

GFW03 W03



side & front elevation - 1:20



ground floor plan - 1:50



external view

current condition:

estimated late C20 casement oriel window painted shut, unable to easily open

proposed replacement unit:

3 light oriel window unit to be replaced with like for like timber unit

replacement unit to contain leadwork to match existing

slimline double glazing to remove the need for any further secondary glazing



external view



internal view



Revision:

Collaborating with: Linda Behan

Job: Drawing: 997 10-02

Project:
Whitfield Farmhouse,
Hungerford Lane, Shurlock
Row, RG10 ONY
Drawing:
GFW03 W03

Date: Status: Mar 24 planning
Drawn By: Checked By:



Colony Architects Ltd.

+44 (0)118 380 0328 hello@colonyarchitects.com colonyarchitects.com

1:20 0.4m 0.8m 1.2m 1.6m 2.0m 1:50 1m 2m 3m 4m 5m