

meters

NOTES


ALL SIZES, DIMENSIONS, QUANTITIES TO BE CHECKED ON SITE PRIOR TO MANUFACTURE, FABRICATION OR ERECTION.

DO NOT SCALE FROM DRAWING.

ALL LEVELS ARE APPROXIMATE AND ARE TO BE CHECKED ON SITE BY CONTRACTOR PRIOR TO COMMENCEMENT OF WORKS.

REPORT ANY ANOMALIES IMMEDIATELY UPON IDENTIFICATION.

IF IN DOUBT - ASK.



## CLIENT

JACK OBERLANDER 1/2 5 DOUNE QUADRANT GLASGOW G20 6DE

## PROJECT

INTERNAL ALTERATIONS AT 1/2 5 DOUNE QUADRANT GLASGOW

DRAWING	SCALE
HALL ROOM LAYOUT -	1:50 @ A3
SKETCH PROPOSAL	ı

## STAGE

RIBA STAGE 2

DRAWING NO	DATE
L(80)SK1	MAY 23