

Cranford Design Ltd.

Architectural Services Centaur House Ancells Business Park Ancells Road Fleet GU51 2UJ

Date -March 2024



15 Hawthorn Way Bisley

A survey of the roof area was carried out when the property was surveyed.

No bat droppings were discovered or seen on external surfaces.

In addition, the property has bitumen felt.

We are obviously not qualified ecologists therefore if evidence is discovered before or during the build professional assistance will be sort.

We believe the property is also greater than 200m from the closest woodland.

The property is situated within a residential estate.





Regards Dave Gill