

## NOTES:

A. All historic fabric and features to be retained and reinstated except where otherwise noted

B. All existing timber floor boards to be retained. Where noted on plan boards to be carefully lifted to allow running of services and insulating floor voids. Damaged planks to be replaced where necessary.

C. All existing retained windows to be be fitted with secondary glazing D. Existing windows to be retained and refurbished except where otherwise noted on

plan. E. All repairs to historic fabric and features to match existing profiles and materials i.e. doors, architraves, skirtings, dado rails and cornices

F. Defective areas of plaster to walls and ceilings to be cut out to a sound base and repaired and made good to match existing G. All existing fireplace's mantels to be retained and restored except where otherwise


noted H. Existing services to be stripped out and re-serviced discretely and sympathetically

throughout I. All modern style radiators to be removed and replaced to be in keeping with the character and the period of the property

## KEY:

- Historic Stables and Carriage House to be refurbished and (01) later addition slate roof to be replaced. New insulated mansard slate roof with raised ridge height by 500mm, to allow forming Student accommodation at the mezzanine level
- (02) Reinstated historical pediment with central arched timber <sup>/</sup> sash window and brickwork to match existing
- (03) Existing timber Carriage door to be altered to four panels to allow stacked opening to sides with fixed metal frame glazing behind
- 04 Ruined Servant's Cottage to be re-roofed with a new insulated state pitched roof to ellow for new insulated slate pitched roof to allow forming Student accommodation at the mezzanine level.
- (05) New timber frame glazed link-corridor
- openings to reinstate the original service yard

(16) Later addition raised floor and block work wall to be removed and area to (07) New accessible link / entrance building with dark (12) Historic Servant's cottage masonry be reinstated to its original level as part of the original butlers's room. grey zinc flat roof wall with 3 No. reinstated original between the principle house and the Stables Later addition glass panelled timber arched door's openings. Doors to block. Clear glazing to allow the reading of 08 New brick parapet to match existing brickwork and bond with stone coping to gable end of door to be removed and opening the historic Servant's cottage masonry wall rooms in solid timber and bond with stone coping to gable end of reduced to provide high level top hung behind with reinstated original arched door's (13) Lightweight self supporting roof stable block timber window structure to new Oratory infill. Roof to 09 New stone coping over the existing masonry wall raised by two brick courses to form 1:100 be covered in slates with west facing (06) Later addition 20th c. coal and wood store, clerestory windows concealed box gutter behind. Brick reclaimed pantry and servant's lounge removed allowing 2m 2m 0 (10) New batten roll lead dormer. New dormer to be Existing louvered opening to be (14) plan-layout. Area to be infilled with a fitted with a double glazed 3 over 6 panel timber enlarged for MVHR air intake light-weight self supporting roof covering and sash window, timber surrounds and slate new floating ground floor slab bearing on Existing window to be reopend and sill cladding to cheeks of dormer. (15) lowered to provide new doorway into screw pile foundations. New batten roll lead dormers to be fitted with (11) accessible toilet 28/03/24 Planning Application double glazed timber casement windows and finished with slate cladding to cheeks of date: issue: dormers



## Proposed Section S05 1:100 @A1

			Project Grandpont Hou	se	
			Drawing Proposed Section	on S02	
			Drawing No. GH(20)A15		
6m	8m	10m	Job No.	Date	Scale
			GH	12.22	1:100@A1
			1st Floor, 59 Charlotte Street London W1T 4PE, UK		otudio
-			T +44 (0)20 3754 7431 M +44 (0)77 9669 4196 E info@studiostassano.com		stassano
revision:			www.studiostassano.com		<b>SIASSAI IU</b>