
Current driveway entrance

Proposed approximate driveway entrance location and hedging to be removed Turnarou ntained old driveway entrance

## Visibility



## Comments

- There will need to be removed a section of hedge from the highway boundary for the opening (primarily made of brambles, ivy and sickly hawthorn), and pampas grass and a shrub from inside the property. There are no trees impacted by this work. Note: the tree showing at the side of the house was removed 2 years ago following approval.
- As the cars are either nearing the junction or coming from the junction, their speed should be decreased from the average speed on the road to nearer 20 miles per hour. Therefore the estimated visibility of between 25-30 meters should be adequate rather than 43. 43 would mean removing most of the hedge along the road, which would not be advantageous to the wildlife or the appearance of the conservation area.