
	CONSTRUCTION KEY
	New Walls
	Masonry - brickwork
$\overline{\vee}$	Masonry - blockwork
	Stud - Timber/ Metal, as noted below
	Ceiling
	Overhead feature e.g. beam/ rooflight/ etc.
	New beam
	<u>Drainage & Mechanical</u>
мн	Manhole
\bigcirc	Inspection Chamber
G	Gully
	Drainage Channel
—>—·	Existing below ground drainage (assumed)
<u> </u>	New ø100mm below ground drainage run
•	Soil Pipe (SVP or Stub Stack)
O RWP	Rain Water Pipe
*	Water supply/ tap
RAD 0	Radiator
\boxtimes	Extract/Supply Fan



ARCHITECTS + INTERIOR DESIGNE SAMPSON
A S S O C I A T E S
D Unit CC413, Workspace Cocoa Stud
+44(0)20 7394 8850
sampsonassoc

0 1 5 10m