	Custom h	eack panel location to fit		possible
	office doo	f		Cleaners Closet sh
				room
Proposed new HVAC system to	safe and			Fire Strategy must
be installed in same location as	safe and comms cabinet			Community Banker
existing				door
	DG 009 Elec St	CInrs St		Ability to see into m
	14 14 1 1 1 m²	2 m²		glazing
		G 006		
	Disabled WC (Staff) Office 8 m²			
			1200	
	1773			
	DG 005			
	DG 004		006	
	s a sa			
	Coin Coin Coin Coin Coin Coin Coin Coin		Meeting Room	Smaller bespoke table to allow for wheelchair access
	685 930 650		10 m²	
	11			
	DG 003		DG 002	
	Staff Room		<i>_</i> - < _	
	13 m²			
		12		
			2	
		Lobby 44 m²		
		DG 001		
Wall to be infilled, to be flushed	Frosted vinyl in staff room	\triangle	New Disabled Access Call	
with DDA kitchenette unit	Frosted vinyl in staff room window for privacy	ENTRANCE	Assist Button required for main	
			entrance	

Banking Hub Design Checklist Checked Comments Ability to see into meeting room via areas of Yes glazing PO Counter end gate must be hinged against Yes counter and open outwards All FOH areas must be visible from Counter Area Yes PO Counter visible from main entrance door Yes Customer waiting area should be located away from front door and close to meeting room The Counter Queue should not obstruct the main Yes entrance door & secure staff door Layout should achieve a logical customer flow Yes The Office must be minimum 4.5sqm and only Yes accessible from behind the counter Office door must open outwards Yes Safe and Coin Cabinet must not be visible by Yes customers when door is open Office must not have a window - exceptions for existing to include intruder bars Meeting Room must be 9.5sqm with space for wheelchair turning circle Meeting room door must open inwards to the wall Yes There must be a 1.2m route from door pass the Yes end of the table Community Banker chair must be nearest to the Yes There must be a DDA compliant WC facility Yes Staff Room should contain a window where Yes possible Cleaners Closet should be separate & lockable Yes room Fire Strategy must comply with regulations 12.1m Yes Community Banker chair must be nearest to the Yes Ability to see into meeting room via areas of Yes glazing

 Meet & Greet Unit (Not Required for this Site) Positioned to achieve maximum visbility and impact from entrance 3. External ATM (Not Required for this Site) 4. Double Counter with TCR 5. Screen & Gate for Counter End Queue Barrier Post 7. Self-Service Area (Not Required for this Site) Writing Desk 9. Enclosed Meeting Room With seating for 3 people and storage credenza 10. Secured Office With safe and standard POL office fitout & supply 11. Staff Kitchen Standard POL kitchen fitout & supply 12. Staff Lockers 13. Table and Chairs

14. WC

Areas Public Areas Back-of-House Areas

Residual Areas

Room Occupancy

Staff Room 3 Persons 3 Persons Meeting Room 20 Persons (2 Members of Staff & General Public) Banking Hall

to be discussed with Client

The layout is based upon Banking Hub Manual 6.0

MEP Key

Gas Supply

Electrical Supply Water Supply

Incoming BT Copper Cable Soil Vent Pipe

Red Line Boundary

0.5 0 0.5 1 1.5 2 2.5



DISCLAIMER NOTES:

THIS DOCUMENT IS COPYRIGHT OF THE ORIGINATOR AND MUST BE TREATED AS

THIS DOCUMENT MUST NOT BE ALTERED, REPRODUCED OR DISTRIBUTED WITHOUT

PRIOR WRITTEN CONSENT OF THE ORIGINATOR THIS DOCUMENT MUST NOT BE ALTERED - THE ORIGINATOR ACCEPTS NO RESPONSIBILITY FOR ANY DISCREPANCIES ARISING AS A RESULT OF THE

ORIGINATORS INFORMATION BEING ALTERED BY OTHERS ANY DISCREPANCY MUST BE REPORTED TO THE ORIGINATOR

ALL DIMENSIONS MUST BE CHECKED ON SITE PRIOR TO COMMENCEMENT OF ANY RELATED WORKS

THIS DOCUMENT MUST BE READ IN CONJUNCTION WITH ALL SUPPORTING DOCUMENTS PRODUCED BY THE ORIGINATOR AND OTHER PROJECT DISCIPLINES

THE ORIGINATOR ACCEPTS NO RESPONSIBILITY FOR THE ACCURACY OF BACKGROUND INFORMATION PRODUCED BY THIRD PARTIES - THIS MUST BE TREATED AS INDICATIVE ONLY

USERS OF THIS DOCUMENT ARE RESPONSIBLE FOR CHECKING WHICH REVISION IS

THE DOCUMENT STATUS "INFORMATION" OR "PRELIMINARY", INDICATES THAT THIS DRAWING IS FOR REFERENCE PURPOSES ONLY - THE ORIGINATOR WILL ACCEPT NO RESPONSIBILITY FOR THE COMPLETENESS OF INFORMATION UNDER THIS STATUS

THE DOCUMENT STATUS "RECORD" OR "AS BUILT" HAS BEEN PREPARED, IN PART, BASED UPON INFORMATION FURNISHED BY OTHERS. WHILE THIS INFORMATION IS BELIEVED TO BE RELIABLE, THE ORIGINATOR ASSUMES NO RESPONSIBILITY FOR THE ACCURACY OF THIS "RECORD" OR "AS BUILT" DOCUMENT OR FOR ANY ERRORS OR OMISSIONS THAT MAY HAVE BEEN INCORPORATED INTO IT AS A RESULT OF INCORRECT INFORMATION PROVIDED TO THE ORIGINATOR. THOSE RELYING ON THE "RECORD" OR "AS BUILT" DOCUMENT ARE ADVISED TO OBTAIN INDEPENDENT VERIFICATION OF ITS ACCURACY

DRAWING NOTES:

CDM REGULATIONS 2015 SIGNIFICANT OR NON-OBVIOUS RISKS AND RISKS WHICH ARE DIFFICULT TO MANAGE ARE IDENTIFIED ON THIS DRAWING USING THE FOLLOWING SYMBOL IDENTIFIED TO THE RIGHT WITH BRIEF ACCOMPANYING TEXT. FOR FURTHER DETAILS OF THE RISKS IDENTIFIED BY DESIGNERS, REFERENCE SHOULD BE MADE TO CDM HAZARD REGISTER.

P04 Planning Issue P03 Full Technical Design Issue P02 Full Concept Design Issue REV DESCRIPTION

22/04/24 HK JP 02/04/24 HK JP 04/03/24 BK JP 05/02/24 ZS JP DATE BY CHKD

TEL NO: 0117 244 2500



TOWER WHARF CHEESE LANE BRISTOL BS2 0JJ

CLIENT:

ORIGINATOR:

WWW.RIDGE.CO.UK



IN ASSOCIATION WITH:



15 Lower Fore Street, Saltash

Proposed GA Layout

DRAWN BY: SCALE: As indicated @ A1 05.02.24 CHECKED BY:

S5 - Suitable for Review and

Acceptance

PROJECT: ORG: ZONE: LEVEL: TYPE: ROLE: NUMBER: REV: 5019069 RDG XX 00 D A 5820 P05