

dwg file. © 2019 DONALD INSALL ASSOCIATES LTD

Please note DIA cannot be held responsible for any errors arising from changes made to an uncontrolled

the drawings, please contact DIA immediately.

9.

4	19-04-2024	ТХН		Replacement timber windows and extent of plaster replacement indicated	
3	05-04-2024	ТХН		Secondary glazing omitted from WG04	
2	20-03-2024	ECL	ТХН	G03 bathroom layout, insulation wall lining, mantlepiece	
1	14-12-2023	HXA	ТХН	Issued for design and cost estimation puposes	
0	11-01-2023	LXW	ТВ	Issued for Planning and Listed Building Consent	
Rev	Date	Dwn	Auth	Revision	
					-

Hat<u>ch Key</u>:

proposed fixtures, fittings or built fabric, proposed to be inserted, as



Extent of plaster damaged by moisture ingress requiring replacement.

(+44) 01244 350 063 chester@insall-architects.co.uk

4M

Revision

4

Basement and Ground Floor Plans As Proposed

HPC.01 2001 Scale (A1) Status

1:50

**C** Construction R Record Rev Date Dwn Auth Revision