



BUILDINGS 1 and 2. KESTREL WAY, WOKING.

BBFF 12840.20

WBC PLAN/2019/0573

CONDITION 21

See email dated 16th December 2020 from McLoughlin Groundwork Ltd., the groundwork/civil engineering contractor, confirming no ground contamination was found and no signs of contamination were discovered as a result of their works.

CONDITION 22

See email dated 16th December 2020 from Brymor Construction Ltd., the main contractor confirming there were no indications of any contaminants in the subsoils throughout the excavation works.

See also below a selection of earthwork/excavation record photographs. A full set of record photographs will be forwarded to the case officer in due course.

pr/bbff/22.12.20





