Garden Lodge - Tree Survey Plan

T11 - Proposed to be Felled

MIXED SPECIES GROUP T6
ASH T7 x2
TREE PROTECTION BARRIER
CHERRY T10
GARAGE SLAB 75.95
DWELLING 1 FFL 76.00
HIMALAYAN BIRCH T8 PROPOSED TO BE FELLED
HIMALAYAN BIRCH T9 PROPOSED TO BE FELLED
MIXED SPECIES GROUP T6
SYCAMORE T15
SYCAMORE T14 PROPOSED TO BE FELLED
SYCAMORE T13
ASH T12
HORSE CHESTNUT T1
LAWSON CYPRESS T11
DWELLING 2 FFL 76.55
GARAGE SLAB 76.45
ASH T16
SYCAMORE T18
SYCAMORE T17
ASH T15
LAWSON CYPRESS T13
BEECH T12
LINE OF LAWSON CYPRESS T14
SYCAMORE T19
GARDEN LODGE
CARE HOME
EAST HILL
Gravel Track
Gravel
Tarmac
Grass
Bushes
Overhead Cable
Wall Ht 1.7
Wall Ht 1.4
PWF Ht 0.7
PWF Ht 1.0
PWF Ht 0.9
BMF Ht 1.0
LLF Ht 1.8
CLF Ht 1.3
Eave Ht 80.93
Ridge Ht 83.73
Eave Ht 81.44
Ridge Ht 84.24
Eave Ht 81.76
Ridge Ht 84.92
Ridge Ht 82.48
Ridge Ht 90.50
+Ridge Ht 90.46
Remains of derelict fence
Edge of Concrete Footpath
Hawthorn Bushes Ht 3.0
Laurel Bushes Ht 3.0
Decking over disused Swimming Pool
Tank on supports
Paving Slabs
R.Wall
Steps
Gate
Post
Kerb
Slope
Store
Garage
TP
SV 73.50
EP