





PHOTO (EXISTING) - ENTRANCE FROM HIGH ROW TO CLARKS YARD - CLARKS YARD NTS @ A1



1:25 @ A1



Row

1233_311

As Shown @ A1 03.12.20

1:25 @ A1

nage pipe	Painted cast iron drainage pipe
rmacy	
50	Graffiti
	Damage to cladding (Marked as orange)

ELEVATION - B-B' - EXISTING CONDTION ENTRANCE FROM HIGH ROW TO CLARKS YARD - CLARKS YARD

0191 440 0034 www.southerngreen.co.uk studio@southerngreen.co.uk

BIM

Tender

Copyright and all intellectual property

rights remain vested in Southern Green L

Rev C

DL3 7QH