

Photographs at 6 Coastguard Cottages





South Elevation 6 Coastguard Cottages



North side of 6 Coastguard Cottages



Communal path to the north side of Coastguard Cottages looking east from 6 Coastguard Cottages



Looking west towards 6 Coastguard Cottage, with house on the left and boot room on the right and gate to 7 Coastguard Cottage.



Boot Room from Bedroom 2. Door to right access to 5 Coastguard Cottages garden and storage room



North facing roofs 6 Coastguards Cottage.



Boot room roof (foreground) and north side of roof to 6 Coastguard Cottages



Boot room roof and roof to adjoining property.



Water ingress to south facing wall in conservatory





Balcony over conservatory.



Water damage to external wall to bedroom 1



Water damage to reveal in south wall between conservatory and living room.