



Taken 18.12.2011
North West corner
Steading prior to complete collapse of roof



Taken 03.03.2020
North East Gable
Steading after roof collapse



Taken 18.01.2011
North West corner
Overview of Steading, Farmhouse & Steading B, prior to roof collapse

MOXON
LONDON
Great Western Studios, 65 Alfred Road, London W2 5EU
t 0207 534 0088 f 0207 534 0099
SCOTLAND
Ardoch, Grathie, Aberdeenshire AB35 5UN
t 01339 742047 f 0207 034 0099
m@moxonarchitects.com | www.moxonarchitects.com

Project		Ardoch Steading	
Drawing Title		Site Photographs	
Status		Information	
Drawn by	EPS	Checked by	
Project No	703	Scale	
Drawing No	050	Date	09.10.20
REV	DATE	DESCRIPTION	DRAWN
			CHK
			Rev. 01