

Removal of the existing corroded railings followed by shot blasting and refurbishment off site and their subsequent re-installation.

The removal of existing asphalt covering and replacement of rotten timbers. The laying of a new asphalt covering. New lead flashing at interface with existing bay window

#### **SHAPE** Architecture

WWW.SHAPEARCHITECTURE.CO.UK

## **FOR PLANNING**

### 10 Bloomsbury Place Brighton BN2 1DA

PROJECT

Front Elevation showing Balcony/Railings

# **Existing/Proposed**

nts

February 2021

SCALE

DATE

#### PL003

DWG. NO.

REVISION

This drawing is copyright Shape Architecture Ltd. The Contractor must not scale from the drawing. All dimensions to be taken from dimension strings. Where any discrepencies are found between dimensions these must be brought to the attention of the Architects for resolution. Where discrepencies exist between reference or assembly drawings and detail drawings the latter take preference.

**FRONT ELEVATION**