

# Windows

Front (south) elevation showing windows to be replaced, outlined in red. 2 on basement level and 2 on ground floor.



10 Ruskin Terrace, G12 8DY



Close ups of basement windows



10 Ruskin Terrace, G12 8DY





10 Ruskin Terrace, G12 8DY





10 Ruskin Terrace, G12 8DY



Basement windows from inside – astragals have been widened in the past from original profile.



10 Ruskin Terrace, G12 8DY

Close up of ground floor windows



10 Ruskin Terrace, G12 8DY





10 Ruskin Terrace, G12 8DY

Ground floor window close up from inside showing notch where astragal has been removed in the past



10 Ruskin Terrace, G12 8DY



Rear (north) Elevation showing bedroom windows to be replaced in red outline.



10 Ruskin Terrace, G12 8DY



Internal view of rear window - multiple alterations over the years including plastic astragals added after the originals were removed.



10 Ruskin Terrace, G12 8DY



Rear Elevation – closer view of window bars





Rear window to be replaced



10 Ruskin Terrace, G12 8DY



### Proposed Replacement Windows

Double glazed sash and case – replica of existing original frame, with vertical astragals reinstated. Photos below are from the supplier (<https://sashwindowsglasgow.co.uk/>) showing the profile that would be used.

