

# Window Bars

Front (south) elevation showing window bars to be removed from windows outlined in red on the basement level. Two can be seen from the street, another is under the flying stair.



10 Ruskin Terrace, G12 8DY

Close up of window 2 & 3



10 Ruskin Terrace, G12 8DY

Window 2 (bedroom)



10 Ruskin Terrace, G12 8DY

Window 3 (bedroom)



10 Ruskin Terrace, G12 8DY

Window 1 (bedroom)



Rear (north) Elevation showing window bars to be removed in red outline.



Top right small window is in the kitchen

Bottom left is a bedroom

Bottom right is a bathroom

These 2 floors belong to the same owner.

10 Ruskin Terrace, G12 8DY

Rear Elevation – closer view of window bars



Rear Elevation close ups of damage to stonework from window bars and cement

