

Photographs to Accompany Decorative Stonework Repair Schedule



1. Leaves to engaged columns



2. Missing string course to column head



3. Missing leaves to entablature of column head



4. Vines and flowers to westerly column head for replicating at east



5. Decorative stone head which has lost all definition



6. Missing leaf to arch base at entrance door



7. Leaf points missing to carved arch base



8. Missing flower to carved arch base



9. Missing pinnacle to gable

Photographs to Accompany Decorative Stonework Repair Schedule - Cont




10. Historic image of gable pinnacle



11. Lions head to rainwater hopper



12. Leaf point missing to engaged column on north elevation



13. Leaf to engaged column on north elevation



14. Missing leaf to column head



15. Decorative stone head to north elevation which has lost most definition



16. Missing leaf to carved stone head



17. Carved stone to north elevation rainwater head which has lost most definition

Photographs to Accompany Decorative Stonework Repair Schedule - Cont



18. Carved entablature to tower



19. Carved head to Annexe buttress



20. Pinnacle to Annexe buttress



21. Example of engaged column to north elevation



22. Example of engaged column to north elevation



23. Annexe buttress



24. Tower Pinnacle