




Site photograph of Purcell elevation 12 (viewport no  $\frac{2}{3008}$  below)







**ELEVATION 3.4 FROM STS SURVEY 26727-IE; Purcell elevation 12** 3008 1:50 @ A I


Drawings are based on survey data and may not accurately represent what is physically present.

Do not scale from this drawing. All dimensions are to be verified on site before proceeding with the work.

All dimensions are in millimeters unless noted otherwise.

Purcell shall be notified in writing of any discrepancies.

**Key Plan** not to scale



Extent of wall penetration to be limited to the extent of the anchor penetrations. Stone to be carefully cut out to limit damage to adjacent stone. Make good any damage around opening. Reinstate matching stone following Purcell specification clause F10.665

## 239945-PUR-00-00-DR-A-3008

25/01/2021 CP CR Issued for LBC

Current 25/01/2021

ISSUE DATE CHECKED DESCRIPTION

CLIENT The University of Oxford

**PROJECT** Reuben College

TITLE Reuben College External Elevations Remedial Works Temporary Works for Support Scaffolding Above Museum Store

SIZE & SCALE AIL

**JOB NUMBER** 239945

**NUMBER** 

**STATUS** 

3008

**REVISION** 

P01.03

