

PROSPECT HOUSE, CHARLTON, RADSTOCK, BA3 5TN

APPENDIX B

Photo 1 - Hallway - damaged stairs and partition wall



Photo 2 – Music Room - damage to floor and walls




Photo 3 – Sitting Room – Timber paneling to be refurbished




Photo 4 – Basement – damaged ceiling and floor joists

