

GROUND MATERIALS



A close-up photograph of a brick wall, showing several rows of bricks in various shades of red and brown, separated by light-colored mortar. The bricks have a rough, textured surface.



A close-up photograph of a brick wall. A large, irregular, light-colored stain or efflorescence is visible on the surface of the bricks, particularly in the center-left area. The stain has a crystalline or powdery appearance. The surrounding bricks are reddish-brown and show some signs of weathering.

Job No: 5623 Drwg No: 2 Revision: E