

Podium Eastern Garden Wall - As Proposed 1:5 for rebuilt section

Garden wall to east side of pond & podium western wall both repaired in damaged area. Damaged area carefully taken down, bricks cleaned of mortar & wall rebuild, reusing same bricks, zinc flashings & concrete copings, with new movement joints to match existing one in podium eastern garden wall, as described in Design & Access Statement

Garden Wall to East Side of Pond & Podium Western Garden Wall

In millimetres	
Garden Wall Repairs St Catherine's College , Oxford. OX1 3UJ	Pendery Architecture & Heritage Ltd 23 Orchard Road Hook Norton Banbury Oxon OX15 5LX d.pendery@btinternet.com 07482 557577
CLIENT St Catherine's College	ALL DIMENSIONS IN MILLIMETRES UNLESS STATED OTHERWISE. DO NOT SCALE FROM THE DRAWING USE GIVEN DIMENSIONS ONLY. ALL DIMENSIONS TO BE CHECKED ON SITE. LATEST REVISION:
Wall Sections - As Proposed	SCALE @ A1 DATE DWG NO. REV As Shown Dec'20 2013/04 © Pendery Architecture & Heritage Ltd DWG NO. REV

400

200

1:5 Scale