

Cusacks Estate, Saintbury


Fireplace in family room (14)



(3) Stairs to be removed seen from below



(2) Stairs to be removed showing door



(1) Stairs to be removed


Cusacks ~~Steps~~ Saintbury



(11) Looking down stairs from Bed 1 to be removed



(12) Attic stairs (new) to be removed




Wood partitions & cupboards Bed 1 to be removed (13)



(13) Solid Bathroom Partition to be removed


Cusacks Street. Saintbury



⑧ Fireplace Bed 3




⑦ Partition in Bathroom



⑥ Slatted Panel to Bath by stairs showing wattle




⑤ Slatted Panel to Bath by stairs



14 Looking down stairs from bed 2 showing away wall



16 Broken window.



15 Ingethock




9 Dwarf wall from Bedr'm 1 (shwr Rmside)



18 Screening to oil tank



17 Blocked window



19 Sundry & Car Port to be replaced