

**REF 5 TREES HEDGES TO BE REMOVED**

**Ref 2 East wall view photo shows trees**

**T1, T2, T3 & T4 roots causing issue with wall  
T5 Needs pruning as around telephone cables**

