











To be extended using matching reclaimed bricks

Portuguese Laurel Border Hedge

New driveway constructed with tumbled block pavers

6 Church Walk

Lawn

No. 3 Church Walk

Uniform edge row of Boxus microphylla

Existing David Austin shrub roses

Existing small shrub tree

Existing Brick boundary to no. 3

Border edged with paving kerbstones to match tumbled block paving

PAVEMENT

ROAD

Existing rose border to remain enhanced with Alliums, Lavandula and Spring bulbs

