

0/2 2 Hampden Terrace Photographs



Wall affected by new high level window. See relevant drawings for details



W8



Front elevation W1-5



Front elevation W1-5



W6



Exterior redundant structure



Exterior redundant structure



W7



W7



W7



Chimney brest on left to be partially removed. Raised floor and boxed in ceiling to be removed to gain full height



Existing transom window



New transom windows to kitchen and living room to mimic this one in bedroom 1

0/2 2 Hampden Terrace Reference Images



No. 13 Hampden Terrace with original sash windows. Design and proportions to be matched with proposed windows to our site