


TYPICAL FLOOR PLATE



PHOTO 1

Masonry jack arch thickness to be investigated

Cast iron column thickness to be investigated

25.07.18	P01	FOR INFORMATION	DP	CH
Date	Rev	Description	Drawn	Chkd
				
Project Brunswick Mill - Feasibility Study				
Title Investigation Works				
Project Number	Drawing Number	Scale @ A3	Revision	
846-02	SK_001	NTS	P01	