

**APPENDIX 2 - LOWER PLEASURE GROUND WALLS, NEWARK PARK – HISTORIC PHOTOS**



Photo 1: Wall in 1920s (Source: Michael Claydon's archive)



Photo 2: Wall in 1940s (Source: Michael Claydon's archive) – shows 2m high wall



Photo 3: Summer House & wall in 1970s pre-works (©Michael Claydon)





Photo 4: Walls in 1979 (©Michael Claydon) – collapsed 18<sup>th</sup>C wall evident to LHS



Photo 5: Summer House and wall in 1970s showing angle of wall brickwork





Photo 6: Summer House wall in early 2000s – cracking evident



Photos 7 & 8: Ogee archway constructed in 1970s from south side (Left) and north side (Right)





Photo 9: Summer House wall post 2021 collapse



Photo 10: Glasshouse and Loggia in 2006