



Plate 17: View of excavated material from TP302.



Plate 18: Detailed view of sidewalls in completed TP302.



Plate 19: Overview of excavated material from TP311.



Plate 20: Detailed view of sidewalls in completed TP311.



Plate 21: View of excavated material at TP312.



Plate 22: Detailed view of sidewalls in completed TP312.



Plate 23: Overview of excavate material at TP327.



Plate 24: Detailed view of sidewalls in completed TP327.



Plate 25: Overview of excavated material from TP334.



Plate 26: Detailed view of sidewalls in completed TP334.



Plate 27: Overview of excavated material from TP338.



Plate 28: Detailed view of sidewalls in completed TP338.



Plate 29: Overview of excavated material from TP346.



Plate 30: Detailed view of sidewalls in completed TP346.



Plate 31: Overview of excavated material from TP354.



Plate 32: Detailed view of sidewalls in completed TP354.



Plate 33: Overview of excavated material from TP359.



Plate 34: detailed view of sidewalls in completed TP359.



Plate 35: Overview of excavated material from TP366.



Plate 36: Detailed view of sidewalls in completed TP366.