

Appendix A - Pre-construction Mitigation & Enhancements

Following the recommendations for mitigation and enhancement detailed in 'Ecological Impact Assessment & Bat Survey Report' by Davies Ecology Ltd.

Bird

- Demolition completed outside of bird season (commenced and completed end of Feb 2021).
- Installation of 5 permanent bird boxes in Feb 2021 prior to commencement of works.
- For additional post-construction mitigation & enhancements see 'Appendix B'.



Ref: Bird 1
North Facing
Vivara Pro Barcelona WoodStone Open Nest
Box
Product Code: 5051054177250
Installed February 2021



Ref: Bird 2
North Facing
Vivara Pro Barcelona WoodStone Open Nest
Box
Product Code: 5051054177250
Installed February 2021



Ref: Bird 3
South facing
Vivara Pro Seville 28mm WoodStone Nest Box
Product Code: 5051054177861
Installed February 2021



Ref: Bird 4
South facing
Vivara Pro Seville 28mm WoodStone Nest Box
Product Code: 5051054177861
Installed February 2021



Ref: Bird 4
South facing
Vivara Pro Seville 28mm WoodStone Nest Box
Product Code: 5051054177861
Installed February 2021

Dormouse

- Destructive search for dormice carried out in rubble piles 1,2 & 3 under the supervision of an ecologist from Davies Ecology Ltd in September 2019 and re-located to ref Reptile 1 & 2.
- Installation of 5 permanent dormouse boxes.



Ref: Dormouse 1
Installed April 2020



Ref: Dormouse 2
Installed April 2020



Ref: Dormouse 3
Installed April 2020



Ref: Dormouse 4
Installed April 2020



Ref: Dormouse 5
Installed April 2020

Bat

- Demolition completed outside of bat season (commenced and completed late Feb 2021)
- Installation of 4 bat boxes pre-construction.
- Low impact lighting design detailed in document 'Lighting Design The Barn 007'
- For additional post-construction mitigation & enhancements see 'Appendix B'.



Ref: Bat 1
South facing
Greenkey 695 Medium Bat Box - Natural Wood
Installed April 2020



Ref: Bat 2 & 3
East & South Facing
Greenkey 695 Medium Bat Box - Natural Wood
Installed April 2020



Ref: Bat 4
South facing
Greenkey 695 Medium Bat Box - Natural Wood
Installed April 2020

Reptile

- Destructive search for reptiles carried out in rubble piles 1,2 & 3 and other areas of vegetation on site under the supervision of an ecologist from Davies Ecology Ltd in September 2019 and re-located to ref Reptile 1 & 2.
- Grass and vegetation on-site strimmed in phases from September 2019 and maintained near ground level since.



Ref: Reptile 1
Stone pile relocated from rubble piles 1,2 & 3 under the supervision of an ecologist September 2019



Ref Reptile: 2
Stone pile relocated from rubble piles 1,2 & 3 under the supervision of an ecologist September 2019

Badger

- All excavations to be covered out of working hours and means of escape provided where appropriate