

10 Park Quadrant – Schedule of Photos:



1. General Exterior – Northeast



2. General external view – Southeast



3. External connection to SVP – to be retained.



4. General photo of existing WC window



5. Service bulkhead below window to be removed – Contains hot water cylinder



6. WC – to be removed



7. Urinal – to be removed



8. Whb's – to be removed



9. Step at door threshold due to raised access floor which conceals existing drainage installations – to be removed and original floor levels reinstated.



10. Photo at window and existing false ceiling – to be retained.