

**Appendix 6**

**Examples of rotting windows**

**No 1 Tregonhayne Court**




**External window 7**

**Rotten wood and covered by black paint**





External window 1



Rotten wood and covered by black paint

External window 2





External window 3

Rotten wood and covered by black paint

External window 4





**External window 5 - Rotten wood and covered by black paint**



Internal window 1 - Rotten wood and covered by black paint





**Internal window 1 - Rotten wood and covered by black paint**

