


General left side photograph of property



Left side of property, lounge, sitting room, and bedroom one



Main entrance door leading to entrance hallway, conservatory, stairs to 1st floor and bedroom four



Centre of property, study, bedroom three and connecting corridor



Right of property, kitchen/dining room, access to cellar, shower rool larder, W.C., bedroom two and bedroom five room,




Far right of property, garage, store and access to parking at the rear of the site



S Far right of property, bottom of mono pitch roof and right hand side of modern garage door

Junction of 19th Century mono pitch roof to end gable of assumed outbuilding with south facing arch within see photo schedule PS/03



Looking East of south wall showing bulging of wall above cill level

Existing Front Elevation (West) at 1:100 Scale



South gable elevation with sagging mono pitch roof, bulging of wall below roof and structural cracking to bottom left of window.



View of Greta House looking north down South Hill



General right side photograph of property

Photograph identification drawing of front elevation



Structural crack forming going through dental course and 19 courses below - property last decorated June 2017

SYR Consultant
Date

EMAIL: rsyred@syrconsultants.com
TEL 01243 940730 MOB 07850122634
TANGMERE, WEST SUSSEX, PO20 2HZ
7 NETTLETON AVENUE,
SPITFIRE HOUSE,

OLITAIT.	EMAIL: rsyred@syrconsultants.com	TEL 01243 940730 MOB 07850122634	TANGMERE, WEST SUSSEX, PO20 2H	7 NETTLETON AVENUE,	

Hampshire SO32 3PB	Droxford	South Hill	Greta House	Mr and Mrs P. Hudson	

DRAWING TITLE:		

Greta House

front elevation January 202	Filotograpilic scriedule of

Srs	CHECKED:	RCS	DRAWN:	
	DRAWING NO:	2021/01/01	JOB NO:	
	REV:	As Shown @A1	SCALE:	

© SYR Consultants.com

DATE: Jan 2021