Arboricultural Impacts Impacts				N
Trees to be removed 5 Groups / Hedges to be removed (Partial removal of groups) 0 (0) Trees with proposed incursions into RPAs 0	+	+	+ + W	W NNW NNE NE
Groups / Hedges with proposed incursions into RPAs 0 Trees that will require pruning 0 Groups / Hedges that will require pruning 0				W SSW SSE SE
Trees to be transplanted 0 Groups / Hedges to be transplanted 0 Tree Work Schedule			Ind	icative only
Tree No Species Works Category 11 Leyland Cypress Fell to ground level U				
12 Leyland Cypress Fell to ground level U 13 Leyland Cypress Fell to ground level U				
16 Leyland Cypress Fell to ground level B1 17 Leyland Cypress Fell to ground level B1 All tree work is to be undertaken in accordance with British Standard BS 3998:2010 Tree work - Recommendations.		H2		
All arising's are to be removed and the site is to be left as found. Care is to be taken of the ground around retained trees to make sure that it does not become compacted as a result of tree surgery operations. No equipment or vehicles such as timber lorries, tractors, excavators or cranes shall be parked or driven beneath the crowns of	+		+	4
any retained trees, to prevent subsequent compaction and root death. No. of individual trees to be removed		30		
U A B C 3 0 2 0			16	
No. of groups / hedges to be removed U A B C				
0 (0) 0 (0) 0 (0) 0 (0) () = Partial removal of a groups Arboricultural Method Statement				
All tree work is to be undertaken in accordance with British Standard Please refer to Arbtech Consulting Ltd. Tree Schedule, Arboricultural Method Statement and Tree Protection Plan, for full details of all surveyed trees and how all aspects of the development maybe	G3			
surveyed trees and how all aspects of the development maybe implemented without detriment to retained trees.	+	+	THE REPORT OF THE PARTY OF THE	\dashv
	24			
		15		
				4
		0		
		9 130		ARBTECH
				Unit 3, Well House Barns, Chester, CH4 0DH https://arbtech.co.uk, 01244 661170
				Project: Woodlay Farm,
				Herodsfoot, Liskeard, PL14 4RB
	G1 C			Client: Over the Moon
				Drawing: Arboricultural Impact Assessment
				Based on: Site Plan & Topo
				Drawing No: Arbtech AIA 01
		3		Date: Scale: Drawn: Dec 2020 1:200 @ A1 DCG
				Key: Tree Nos.: Tree Canopies: Trunks:
				RPAs: Category 'U' trees: Category 'B' Category groups: Category 'C' trees: Category 'C' groups:
+	+	+	+	Trees to be removed: All dimensions should be checked on site. No dimensions are to be scaled from this drawing.
0m 1m 3m 5m 10m 15m	20m			Please notify us of any discrepancies found. Arbtech Consulting Ltd. cannot be held responsible for inaccuracies the base drawing in which this plan is based. This drawing is designed to reflect the principles of the layout or design only, and relates only to the protection of retained trees. This drawing is not to be read as a definitive part of the engineering or construction designs or method statement An architect or structural engineer should be contacted over any matters of construction, detailing or specification and for any standards or regulatory requirement relating to proposed structures, hard surfacing or underground
				services. This drawing was produced in colour - a monochrome copy should not be relied upon. © Arbtech Consulting Ltd, 2020