

Photographs



Figure 1 - Collapsed arch to boundary wall



Figure 2 - Rear of Boundary wall



Figure 3 - Cracking to front



Figure 4 – Porch



Figure 5 – Cracking to chimney



Figure 6 - Separation between chimney & wall



Figure 7 - Cracking above RHS flank wall window



Figure 8 - Blown wall finish



Figure 9 - 1st floor bedroom



Figure 10 - Cracking at the junction of ceilings/walls