



01 – Neighbouring shed in background, bund to be removed



02 - Bund to be removed, menage to be reduced by 4.5m



03 – View towards site entrance, muck heap to be relocated behind field shelters



04 – Field shelters, hitching rails and muck heap



05 – Menage



06 – Studios to left, livery stables to right and rear



07 – Fitness studios



08 – Rear of stables



09 – View towards house across yard