

East Elevation

West Elevation

North Elevation

Planning and Heritage Statement

Location

Chamusca, The Green, Pulham Market, Norfolk IP214SJ

Designation

Grade 2 Listed

First listed Feb 1977 entry number 1050224

C17 timber-framed. Roughcast. Thatched roof with gabled ends. Two storeys and attic (attic window in gable end). Three windows. Wayside has C18 three-light wood mullion/transom casements and modern glazed door. Charmlsca has modern three-light casements, modern segmental ground floor bay window, and modern "Tudor" style oak door.

Proposals


To replace the existing modern flat roof over the existing Utility room with a tiled pitch roof more in keeping with the dwelling and its historic significance.

Schedule


Carefully remove existing flat roof structure and remove from site. Form new hipped tiled roof and provide new valley into existing lean too roof just below the existing thatch. Provide new clay tiles to match the existing. Provide new block facias soffits and guttering all to match existing.


Conclusion.

These proposals offer the opportunity to enhance the existing Listed Building and remove a more modern structure that is currently not in keeping with the significance of the building.



Floor Plan





Site Plan 1 / 200

Location Plan 1 / 1250



NOTE

The client should be aware of his/her statutory requirement to appoint a principle designer and principle contractor under the <u>CDM 2015</u> regulations.

Peter Codling Architects does not undertake this H&S role unless specifically appointed.

PLANNING

PETER CODLING ARCHITECTS 7 THE OLD CHURCH, ST. MATTHEW'S ROAD, NORWICH, NR1 1SP Tel: 01603 660408 Email: office@petercodlingarchitects.co.uk

Chamusca Pulham Market Mr and Mrs Smith

Proposed Plans

SCALE 1/50 1/200) 1 / 1250 @ A1
_{ЈОВ NO} 6387	02
DATE july 2021	DRAWN BY

THIS DESIGN IS THE COPYRIGHT OF PETER CODLING ARCHITECTS AND MAY NOT BE ALTERED, PHOTOGRAPHED, COPIED OR REPRODUCED WITHOUT WRITTEN CONSENT.

ALL DIMENSIONS ARE TO BE CHECKED BY THE GENERAL CONTRACTOR ON SITE AND ANY DISCREPANCY CLARIFIED BY THE ARCHITECT BEFORE THE