



THORNBANK VIEW 1 - BESIDE SOMERSET COTTAGE



THORNBANK VIEW 2 - BESIDE SOMERSET COTTAGE

NOTE - NO WINDOWS AND SOLID/DISTINCT SITE BOUNDARY



THORNBANK VIEW 3 - BESIDE SOMERSET COTTAGE



EXAMPLE OF QUALITY HISTORICAL DWELLING WITHIN BRAEMAR

NOTE - MATERIALS, CONSERVATION ROOFLIGHT, DORMERS, MASSING + PROPORTIONS



EXAMPLE OF QUALITY HISTORICAL DWELLING NEAR BRAEMAR

NOTE - MATERIALS, CONSERVATION ROOFLIGHT, MASSING + PROPORTIONS



EXAMPLE OF QUALITY HISTORICAL DWELLING NEAR BRAEMAR

NOTE - MATERIALS, DORMERS, EAVES DETAIL, CONSERVATION ROOFLIGHT, MASSING + PROPORTIONS