

**Section A - Pictures of existing crittal windows at the rear, in poor condition and unable to close fully.**





**Section B – picture of the rear of the property as is and proposed porch in fill visual**



## Section C – installation of French patio doors



**Section D – pictures to accompany Alterations to internal layout**



Point No 1. Current cupboards in entrance hall removed to create new kitchen entrance



Point No 2. Existing kitchen doorway kept and create small new w/c



Point No 3. Current kitchen larder to be removed. Also shows redundant chimney breast to be removed.



Point No 4. Current separate bathroom and toilet, remove wall between to create one bathroom