

OLD MANOR FARM
READS LANE
CUBLINGTON
BUCKS
LU7 0LE

PHOTOGRAPHIC SCHEDULE

NOVEMBER 2021



stud wall
to be
removed



stud wall
to be
removed

Photo of landing from shower rm

Photo of landing back to shower rm



stud wall
to be
removed

Photo within bedroom 1



stud wall
to be
removed

Photo within bedroom 2



Photo within master bathroom facing stud wall to be removed



Photo within family bathroom facing stud wall to be removed




Photo within family bathroom showing wall to be retained opposite stud wall to be removed