operations commencing.

Whilst every care has been taken to ensure the accuracy of this survey, due to the age of the premises, non-exposure of the structure, occupancy, building methods & materials used, some assumptions have been made necessary.


Specific areas must be checked on site prior to manufacture of fittings, ordering of materials & equipment & commencement of building operations.


Any conflicting information found on the drawing must be reported for clarification.

Under the 'control of asbestos regulations 2012' for buildings constructed before 2000, the building owner / tenant is legally obliged to manage the asbestos content within the premises. This is accomplished with an asbestos survey which will identify & make recommendations on how to manage any asbestos found. This specialist survey is not within the remit of Ampersand Associates Ltd & the client is strongly advised to check if there is already a suitable report available. If not, a 'Management' asbestos survey should be instigated by the client to cover the entire building, with a further 'Refurbishment & Demolition' survey being carried out, targeting all areas affected by any proposed works. These surveys are to be made readily available prior to any

All drawings produced adopt the principals of prevention in accordance with CDM2015 regulations. Hazards where foreseen have been considered and either designed out or managed where feasible. Any and all associated 3rd party drawings and designs must

also take into account the CDM2015 principals of prevention as part of their production.





commercial architectural design. and then some

Travis Perkins 3 Roy Richmond Way Epsom KT19 9AF

ampersand

e: amp@ampersand-associates.com

w: ampersand-associates.com

Cannons Mill Lane Bishops Stortford Hertfordshire

CM23 2BN

Proposed

Perimeter Fencing & Gate Detail 1:20 @A1 June 21

DATE: DS/LT20 DRAWN: DRAWING No:

8179/07

SCALE:

1.5m

1:20 SCALE BAR